

# IAQ Best Practices Seminar

HVAC, Environmental Factors &

Critical Measurements

# The Evolution of Commercial HVAC Systems





are rendering satisfactory service in every State of the Union and in the Dominion of Canada

Finally, the claims for a unit ventilator are tested by daily performance.

The very first Nesbitt units-installed in the

Park Avenue School, Pleasantville, N. J., in 1917-

are still in operation and giving satisfactory service.

Since then more than 85,000 successful installations

have carned for Nesbitt the hearty approval of

school officials, architects and engineers.

Nesbitt Sales and Service are nation-wide

through offices of John J. Nesbitt, Inc.,

and American Blower Corporation . . . and

in Canada through Canadian Sirocco Company, Ltd.

Publication 261-Section A. Printed in U. S. A. 1-50-17.5M

JOHN J. NESBITT, INC., MANUFACTURERS, PHILADELPHIA 36, PA., U. S. A.

John J. Nesbitt, Inc., and are guaranteed to be free from defects in manufacture and

operation. Nesbitts will, after a year's use, accept the return and refund the full purchase

price of any NESBITT SYNCRETIZER that has failed to perform as represented.





# If you wanted "V"



# If you wanted "V"



### Then came A/C



## Then came A/C










### **Equipment Management**







### **Equipment Management**



#### Then

#### Now

- ✓ Low pressure steam
- ✓ Hot water
- ✓ Radiators
- ✓ Unit ventilators
- ✓ Exhaust fans
- ✓ Steam traps
- ✓ Manual control
- ✓ Pneumatic control

- VAV's VRF's
- WSHP's
- GWSHP's
- OAU's
- AHU's
- CUV's
- HRU's
- FC's
- VFD's
- Split systems DX units
- Direct ventilation
- Blended ventilation
- Dehumidification
- Circuit setters
- Valve actuators
- Condensate pumps
- Chillers
- Cooling towers
- Ice storage
- LON
- **BacNet**
- **ATC**
- BAS
- TCP/IP (network attached)
- Web native


#### All this on order to...


Introduce Heat
Reject Heat
Add Clean, Fresh
and Dry Air


# Change Factors That Contribute to Mold Growth

- ✓ Positive ventilation
- ✓ Air conditioning
- ✓ Energy efficiency
- ✓ Emission controls
- ✓ IEP's

# Troubleshooting Approach Linear Systematic











- Issue began from an IAQ complaint
- Excessive humidity levels

- Multi-story facility built in 1932
- Steam boiler/hot water
- Some split VRF systems
- Recent HVAC renovation
- Chilled water
- UV's with economizer and dehumidification
- Wireless control systems













- No boiler controls
- Elevated steam pressure
- 260 gallons of water steamed off per day!
- Pressurized crawl space
- Numerous floor penetrations
- Numerous communication failures in new wireless ATC system
- No high condensate sensors in AHU's

#### Case Study - Outcome

- Re-establish boiler controls
- Return steam pressure to normal levels
- Boiler make-up water at 70 gallons per day
- Ventilate crawl space
- Seal floor penetrations
- Still working to correct communication failures in new wireless ATC system
- Service classroom UV
- Classroom RH levels returned to normal
- Install and program condensate sensors in AHU's

# Clean Electrical Power and Network Consideration for Optimum Controls Performance

- Legacy transforms, outdated wiring, properly sized neutrals
- Flat networks

# Knowledge and diligence will avoid this...







### Thank You!

Questions...
?